

DIVISION OF ENVIRONMENTAL PROTECTION

GASTON CAPERTON GOVERNOR 1356 Hansford Street Charleston, WV 25301-1401 LAIDLEY ELI McCoy, Ph.D. DIRECTOR

September 25, 1995

CERTIFIED MAIL
RETURN RECEIPT REQUETED

Frances Wildenstein, Fleet Manager Coyne Textile Services P.O. Box 9097 Huntington, WV 25704

Dear Sir/Madam:

Enclosed is a copy of the **Compliance Schedule Evaluation Report** completed by representatives of the Chief from the Office of Waste Management. This report is based on the inspection conducted on March 1, 1995.

Please refer to the Notice of Violation for those violations discovered during the course of this inspection. As a result of those violations, this report is being referred for the following action:

 Notice of Violation (NOV)
 Civil and Administrative Penalty (CAP)
 Enforcement Referral

A copy of this report is being transmitted to the United States Environmental Protection Agency (U.S. EPA), Region III, Philadelphia, Pennsylvania.

Thank you for your assistance and cooperation. If you have any questions concerning the inspection or the attached report, please feel free to contact Inspector P. L. Brown at (304) 256-6850.

Sincerely,

Thomas A. Fisher Inspector Supervisor

Thomas a. Fil

TAF/kw

cc:

Jeanne Sofield, U.S. EPA, Region III Inspector P. L. Brown Civil and Administrative Enforcement File

INSPECTION FACT SHEET

COMPANY NAME:

Coyne Textile Services

ID#: WVD052574753

MAILING ADDRESS:

PO Box 9097

Huntington, WV 25704

FACILITY TYPE: SQG/Transporter

LOCATION:

1111 Vernon Street

Huntington, WV

COUNTY: (99)Wayne

COMPANY CONTACT:

Frances Wildenstein, Fleet Manager

PHONE:

(304) 429-5585

PURPOSE:

Compliance Schedule Evaluation (follow-up)

APPLICABLE REGULATIONS: West Virginia Hazardous Waste Management

Act, Chapter 22-18 and 40 CFR, Parts 260-265.

LIST OF CHEMICALS:

[For Small Quantity Generators, list amount of waste, how it is handled and where it goes.]

D001/D018/D039----parts cleaner waste----16 gallons / 6 weeks----Safety Kleen. D001---solvent-soaked shop cloths received from off-site for recycling.

DATE INSPECTED:

March 1, 1995

INSPECTORS:

(1) P L Brown

(2) D Cunningham

(3)

DATE PREPARED:

August 8, 1995

VIOLATIONS_X____

PREPARED BY:

P L Brown

NO VIOLATIONS____

INSPECTION REPORT

On March 1, 1995, inspectors Dave Cunningham and Penny L. Brown, met with representatives of Coyne Textile Services (CTS) at the Huntington, WV facility for the purposes of conducting a follow-up of a compliance evaluation inspection conducted in April 1994. We were met on-site by Kris McCandless of Ogden Environmental, who is continuing with the site assessment begun in 1994. The representative was advised that this inspection would assess the facility's compliance with the WV Hazardous Waste Management Act and the Regulations promulgated thereunder.

The site assessment being conducted by Ogden Environmental initially involved kerosene spilled from an above ground tank. After chlorinated solvents were detected in the soil, these compounds were included in the assessment. The compounds found at the site were identified as tetrachloroethylene (PERC), trichloroethene (TCE), dichloroethene (DCE), methylene chloride, and chloroform.

The primary purpose of this phase of the site assessment was to plot the vertical and horizontal extent of the contamination plume from the kerosene spill. The samples collected were also screened for the presence of chlorinated hydrocarbons. A "Geo-Probe", operated by EnviroSurv personnel was used to collect samples from various depths in approximately 21 locations on the property. Field screening was conducted using a flame ionization detector (FID). Samples were analyzed on-site for BTEX and TPH by EnviroSurv's mobile laboratory.

As a result of this sampling the contamination plume from the kerosene release has been more fully mapped and included in Ogden's "Addendum #1 to the Site Characterization Report". From the map included in Ogden's "Addendum #1", it appears that part of the contamination plume has moved under the shop building. Remediation efforts by OSRC, the initial spill response contractor, were obviously incomplete. A summary of site conditions and risk assessment should be submitted to George Dasher, geologist with WVDEP-Office of Water Resources for further review. A copy of this inspection report is also being sent to Mr. Dasher.

One area near the back door to the shop contained relatively high concentrations of 1,2-dichloroethene (area of concern). This compound is gradually decomposed by air, light, and moisture to form hydrochloric acid. Chlorinated hydrocarbons were detected in the soil, indicating a past occurrence of disposal of hazardous waste. However, levels appear to be well below characteristic levels for hazardous waste. Quantities of chlorinated compounds found in the soil are also well below the USEPA Draft Soil Screening Level Guidance Document (1993) amounts for contaminated soils.

The underground storage tank (UST) which once contained supplemental fuel oil for the gas-fired boiler was re-sampled. While heating oil tanks are not governed under the UST Regulations, previous data indicated the possible presence of PERC / TCE inside the tank. Less than two inches of liquid were found in the tank. A disposable bailer was used to collect tank liquid into a one liter glass bottle for Ogden and into two 40 ml VOA containers as a "split" sample for WVDEP. The WVDEP sample was placed on ice and delivered to the WVDEP-Guthrie Center Laboratory on March 3, 1995 for SW846 Method 8260 analysis. Methylene chloride (17.5 ug/l) was detected in the WVDEP sample. A data qualifier note indicated that methylene chloride was present in the method blank as well as the sample, and that the reported result should be considered to be of questionable value. Ogden's sample was analyzed by Analytical Technologies, Inc. in Pensacola, Florida. Their analysis found no indication of the presence of

chlorinated hydrocarbons. Similar results from both laboratories were obtained indicating that this UST did contain a petroleum substance resembling heating oil and not chlorinated solvents.

The subsurface soil near the UST was sampled using the Geo-Probe. Samples were collected on the calculated down-gradient side at a depth which would be below the bottom of the tank. Again, while the presence of chlorinated hydrocarbons was detected, levels were below both hazardous waste and industrial waste clean-up levels.

Solvent-soaked rags from various customers are still laundered at this facility. I spoke to D J Smith, environmental engineer from CTS's environmental program. I advised him that this inspection was to assess the CTS's compliance with the WV Hazardous Waste Management Act and the Regulations promulgated thereunder. The representative said CTS is re-working their wastewater treatment to more effectively comply with discharge requirements of the Huntington Sanitary Board. The City of Huntington has had complaints before about solvent odors in the sewers near CTS.

We briefly discussed transport and cleaning of solvent-soaked shop rags. The CTS representative referred me to Mr. Bob Schaffer, director of environmental affairs, saying that CTS has written agreements with several states regarding this issue. West Virginia is not among those states having such an agreement with CTS at this time. One of the definitions of an ignitable hazardous waste is a solid waste which "...is not a liquid and is capable, under standard temperature and pressure, of causing fire through friction, absorption of moisture or spontaneous chemical changes and, when ignited, burns so vigorously and persistently that it creates a hazard.\(^{1\text{w}}\) Dirty solvent-soaked towels and rags are solid wastes prior to cleaning. Solvent-soaked rags or towels meet the NFPA Code definition of a spontaneously combustible material:

"Combustible or loose waste materials that are generated by an establishment or process and, being salvageable, are retained for scrap or re-processing on the premises where generated or transported to a plant for processing. These include, but are not limited to, wood shavings, turnings, all types of paper products, soiled cloth trimmings and cuttings, rubber trimmings and buffings, metal fines, and any mixture of the above items, or other salvageable combustible waste materials.² "

The dirty solvent-soaked towels or rags transported and cleaned by CTS are therefore hazardous waste D001, and should be managed as such. Cleaning these solvent-soaked towels or rags to make them re-usable is a form of recycling. Hazardous wastes that are recycled are subject to the requirements for generators, transporters, and storage facilities of paragraphs (b) and (c) of 40 CFR Part 261.6. Coyne Textile Services transports this hazardous waste without proper manifests (non-compliance 1). Coyne Textile Services also stores this hazardous waste without a permit (non-compliance 2) and without complying with the applicable Subparts of 40 CFR Parts 264, 265, 124, 266, 268, and 270 (non-compliance 3). It should be noted that dirty shop towels or rags that do not contain solvent or other hazardous waste and which are to be cleaned and recycled are not solid waste and are not hazardous waste³.

¹40 CFR Part 261.21(a)(2).

²NFPA 1, Chapter 2, definition.

³40 CFR Part 261.1(b)(1).

Shop towels and rags are normally brought to the facility in large laundry bags. During this and other inspections at CTS Huntington we have witnessed these laundry bags, most wet with solvent, being unloaded into wire hoppers. The bags remain in these hoppers until washed (storage prior to recycling). During one previous inspection, inspector Cunningham and I saw wire hoppers full of these solvent soaked laundry bags being stored outside on the back lot. A strong solvent odor emanating from these bags was noticeable from up to 75 feet away. More than one worker at this facility has told us of previous fires at the facility involving these rags. Once washed and dried the rags are transferred to wooden hoppers until folded and packaged for reuse.

During this inspection I saw pieces of a wooden hopper used to contain cleaned rags leaning up against the building by the boiler room door. The hopper pieces were burned and scorched, evidencing contact with fire. Beside the boiler room door and up on the gravel near the UST were charred pieces of cloth shop rags. The cause of this fire is unknown, but is an area of concern since it involved shop rags.

Other than use of a recyclable solvent in the parts cleaner in the shop area, no waste minimization measures were noted at this facility.

The non-compliances cited above are being referred to the administrative enforcement section for further action. The areas of concern discussed above should be addressed to avoid future violations of applicable regulations.

COMPLIANCE EVALUATION

Violations:

The following violations of the WV Hazardous Waste Management Act (§22-18, hereinafter the Act) and the WV Hazardous Waste Management Regulations (47 CSR 35, hereinafter the Regulations) were noted during this inspection:

- Coyne Textile Services presently transports hazardous waste D001 without use of proper hazardous waste manifests, placarding, containers, etc. This is in violation of 40 CFR Part 263 Subpart B and Part 261.6(b) as referenced by Section 6.1 of the Regulations.
- 2. Coyne Textile Services presently stores hazardous recyclable waste without a permit. This is in violation of Section 8(a) of the Act.
- 3. Coyne Textile Services presently stores hazardous recyclable waste without complying with the applicable Subparts of 40 CFR Parts 264, 265, 124, 266, 268, and 270. This is in violation of 40 CFR Part 261.6(c)(1) as referenced by Section 6.1 of the Regulations.

Concerns:

The following areas of concern were noted during this inspection:

- 1. One area near the back door to the shop contained relatively high concentrations of 1,2-dichloroethene. Removal of the kerosene-contaminated soil should eliminate this.
- The cause of fire in the wooden hopper is unknown, but is an area of concern since it involved shop rags.

INSPECTION FACT SHEET

COMPANY NAME:

Coyne Textile Services

Huntington, WV 25704

ID#: WVD052574753

MAILING ADDRESS:

PO Box 9097

FACILITY TYPE:

LOCATION:

1111 Vernon Street

Huntington, WV

COUNTY: (99)Wayne

COMPANY CONTACT:

Frances Wildenstein, Fleet Manager

PHONE:

(304) 429-5585

PURPOSE:

Compliance Schedule Evaluation (follow-up)

APPLICABLE REGULATIONS: West Virginia Hazardous Waste Management

Act, Chapter 22-18 and 40 CFR, Parts 260-265.

LIST OF CHEMICALS:

[For Small Quantity Generators, list amount of waste, how it is handled and where it goes.]

D001/D018/D039----parts cleaner waste----16 gallons / 6 weeks----Safety Kleen.

D001---solvent-soaked shop cloths received from off-site for recycling.

DATE INSPECTED:

March 1, 1995

INSPECTORS:

(1) P L Brown

(2) D Cunningham

(3)

DATE PREPARED:

August 8, 1995

VIOLATIONS_X____

PREPARED BY:

P L Brown

NO VIOLATIONS____

INSPECTION REPORT

On March 1, 1995, inspectors Dave Cunningham and Penny L. Brown, met with representatives of Coyne Textile Services (CTS) at the Huntington, WV facility for the purposes of conducting a follow-up of a compliance evaluation inspection conducted in April 1994. We were met on-site by Kris McCandless of Ogden Environmental, who is continuing with the site assessment begun in 1994. The representative was advised that this inspection would assess the facility's compliance with the WV Hazardous Waste Management Act and the Regulations promulgated thereunder.

The site assessment being conducted by Ogden Environmental initially involved kerosene spilled from an above ground tank. After chlorinated solvents were detected in the soil, these compounds were included in the assessment. The compounds found at the site were identified as tetrachloroethylene (PERC), trichloroethene (TCE), dichloroethene (DCE), methylene chloride, and chloroform.

The primary purpose of this phase of the site assessment was to plot the vertical and horizontal extent of the contamination plume from the kerosene spill. The samples collected were also screened for the presence of chlorinated hydrocarbons. A "Geo-Probe", operated by EnviroSurv personnel was used to collect samples from various depths in approximately 21 locations on the property. Field screening was conducted using a flame ionization detector (FID). Samples were analyzed on-site for BTEX and TPH by EnviroSurv's mobile laboratory.

As a result of this sampling the contamination plume from the kerosene release has been more fully mapped and included in Ogden's "Addendum #1 to the Site Characterization Report". From the map included in Ogden's "Addendum #1", it appears that part of the contamination plume has moved under the shop building. Remediation efforts by OSRC, the initial spill response contractor, were obviously incomplete. A summary of site conditions and risk assessment should be submitted to George Dasher, geologist with WVDEP-Office of Water Resources for further review. A copy of this inspection report is also being sent to Mr. Dasher.

One area near the back door to the shop contained relatively high concentrations of 1,2-dichloroethene (area of concern). This compound is gradually decomposed by air, light, and moisture to form hydrochloric acid. Chlorinated hydrocarbons were detected in the soil, indicating a past occurrence of disposal of hazardous waste. However, levels appear to be well below characteristic levels for hazardous waste. Quantities of chlorinated compounds found in the soil are also well below the USEPA Draft Soil Screening Level Guidance Document (1993) amounts for contaminated soils.

The underground storage tank (UST) which once contained supplemental fuel oil for the gas-fired boiler was re-sampled. While heating oil tanks are not governed under the UST Regulations, previous data indicated the possible presence of PERC / TCE inside the tank. Less than two inches of liquid were found in the tank. A disposable bailer was used to collect tank liquid into a one liter glass bottle for Ogden and into two 40 ml VOA containers as a "split" sample for WVDEP. The WVDEP sample was placed on ice and delivered to the WVDEP-Guthrie Center Laboratory on March 3, 1995 for SW846 Method 8260 analysis. Methylene chloride (17.5 ug/l) was detected in the WVDEP sample. A data qualifier note indicated that methylene chloride was present in the method blank as well as the sample, and that the reported result should be considered to be of questionable value. Ogden's sample was analyzed by Analytical Technologies, Inc. in Pensacola, Florida. Their analysis found no indication of the presence of

chlorinated hydrocarbons. Similar results from both laboratories were obtained indicating that this UST did contain a petroleum substance resembling heating oil and not chlorinated solvents.

The subsurface soil near the UST was sampled using the Geo-Probe. Samples were collected on the calculated down-gradient side at a depth which would be below the bottom of the tank. Again, while the presence of chlorinated hydrocarbons was detected, levels were below both hazardous waste and industrial waste clean-up levels.

Solvent-soaked rags from various customers are still laundered at this facility. I spoke to D J Smith, environmental engineer from CTS's environmental program. I advised him that this inspection was to assess the CTS's compliance with the WV Hazardous Waste Management Act and the Regulations promulgated thereunder. The representative said CTS is re-working their wastewater treatment to more effectively comply with discharge requirements of the Huntington Sanitary Board. The City of Huntington has had complaints before about solvent odors in the sewers near CTS.

We briefly discussed transport and cleaning of solvent-soaked shop rags. The CTS representative referred me to Mr. Bob Schaffer, director of environmental affairs, saying that CTS has written agreements with several states regarding this issue. West Virginia is not among those states having such an agreement with CTS at this time. One of the definitions of an ignitable hazardous waste is a solid waste which "...is not a liquid and is capable, under standard temperature and pressure, of causing fire through friction, absorption of moisture or spontaneous chemical changes and, when ignited, burns so vigorously and persistently that it creates a hazard.\(^1\text{"}\) Dirty solvent-soaked towels and rags are solid wastes prior to cleaning. Solvent-soaked rags or towels meet the NFPA Code definition of a spontaneously combustible material:

"Combustible or loose waste materials that are generated by an establishment or process and, being salvageable, are retained for scrap or re-processing on the premises where generated or transported to a plant for processing. These include, but are not limited to, wood shavings, turnings, all types of paper products, soiled cloth trimmings and cuttings, rubber trimmings and buffings, metal fines, and any mixture of the above items, or other salvageable combustible waste materials.² "

The dirty solvent-soaked towels or rags transported and cleaned by CTS are therefore hazardous waste D001, and should be managed as such. Cleaning these solvent-soaked towels or rags to make them re-usable is a form of recycling. Hazardous wastes that are recycled are subject to the requirements for generators, transporters, and storage facilities of paragraphs (b) and (c) of 40 CFR Part 261.6. Coyne Textile Services transports this hazardous waste without proper manifests (non-compliance 1). Coyne Textile Services also stores this hazardous waste without a permit (non-compliance 2) and without complying with the applicable Subparts of 40 CFR Parts 264, 265, 124, 266, 268, and 270 (non-compliance 3). It should be noted that dirty shop towels or rags that do not contain solvent or other hazardous waste and which are to be cleaned and recycled are not solid waste and are not hazardous waste³.

¹40 CFR Part 261.21(a)(2).

²NFPA 1, Chapter 2, definition.

³40 CFR Part 261.1(b)(1).

Shop towels and rags are normally brought to the facility in large laundry bags. During this and other inspections at CTS Huntington we have witnessed these laundry bags, most wet with solvent, being unloaded into wire hoppers. The bags remain in these hoppers until washed (storage prior to recycling). During one previous inspection, inspector Cunningham and I saw wire hoppers full of these solvent soaked laundry bags being stored outside on the back lot. A strong solvent odor emanating from these bags was noticeable from up to 75 feet away. More than one worker at this facility has told us of previous fires at the facility involving these rags. Once washed and dried the rags are transferred to wooden hoppers until folded and packaged for reuse.

During this inspection I saw pieces of a wooden hopper used to contain cleaned rags leaning up against the building by the boiler room door. The hopper pieces were burned and scorched, evidencing contact with fire. Beside the boiler room door and up on the gravel near the UST were charred pieces of cloth shop rags. The cause of this fire is unknown, but is an area of concern since it involved shop rags.

Other than use of a recyclable solvent in the parts cleaner in the shop area, no waste minimization measures were noted at this facility.

The non-compliances cited above are being referred to the administrative enforcement section for further action. The areas of concern discussed above should be addressed to avoid future violations of applicable regulations.

COMPLIANCE EVALUATION

Violations:

The following violations of the WV Hazardous Waste Management Act (§22-18, hereinafter the Act) and the WV Hazardous Waste Management Regulations (47 CSR 35, hereinafter the Regulations) were noted during this inspection:

- Coyne Textile Services presently transports hazardous waste D001 without use of proper hazardous waste manifests, placarding, containers, etc. This is in violation of 40 CFR Part 263 Subpart B and Part 261.6(b) as referenced by Section 6.1 of the Regulations.
- 2. Coyne Textile Services presently stores hazardous recyclable waste without a permit. This is in violation of Section 8(a) of the Act.
- 3. Coyne Textile Services presently stores hazardous recyclable waste without complying with the applicable Subparts of 40 CFR Parts 264, 265, 124, 266, 268, and 270. This is in violation of 40 CFR Part 261.6(c)(1) as referenced by Section 3.1 of the Regulations.

Concerns:

The following areas of concern were noted during this inspection:

- One area near the back door to the shop contained relatively high concentrations of 1,2dichloroethene. Removal of the kerosene-contaminated soil should eliminate this.
- 2. The cause of fire in the wooden hopper is unknown, but is an area of concern since it involved shop rags.

ATTACHMENT 1: WVDEP SAMPLE RESULTS FOR UST

Client ID: Sample ID: Office of Waste Management

Lab ID:

IV-591030-P GCL9502102

P. L. Brown/K. McCandless Sampled by:

Date/Time Sampled: Date Received: Date/Time Analyzed: Analyzed by:

3/1/95 @ 1230 3/3/95 3/7/95@1416 Dan Arnoid

Project ID:

RCRA

Method: SW846 Method 8260/EPA Method 624

		Result	TDL	<u>Data</u>
Compound	CAS#	ug/L	ug/L	Qualifier
dichlorodifluoromethane	75-71-8		50.0	U
chloromethane	74-87-3		50.0	U
vinyl chloride	75-01-4		50.0	U
bromomethane	74-83-9		50.0	U
chloroethane	75-00-3		50.0	U
trichloromonofluoromethane	75-68-4		50.0	U
1.1-dichloroethene	75-35-4		50.0	U
methylene chloride	75-09-2	17.5	5.0	В
trans-1.2-dichloroethene(E)	156-60-5		50.0	U
1,1-dichloroethane	75-34-3		50.0	U
2.2-dichloropropane	594-20-7		50.0	U
cis-1,2-dichloroethene(Z)	156-59-2		50.0	U
bromochloromethane	74-97-5		50.0	U
chloroform	67-66-3		50.0	U
1,1,1-trichloroethane	71-55-6		50.0	U
1,1-dichloropropene	563-58-6		50.0	U
carbon tetrachloride	56-23-5		50.0	U
benzene	71-43-2		50.0	U
1.2-dichloroethane	107-06-2		50.0	U
trichloroethene	79-01-6		50.0	U
1.2-dichloropropane	78-87-5		50.0	U
dibromomethane	74-95-3		50.0	U
bromodichloromethane	75-27-4		50.0	U
cis-1,3-dichloropropene(Z)	10061-01-5		50.0	U
toluene	108-88-3		50.0	U
trans-1,3-dichloropropene(E)	10061-02-6		50.0	U
1,1,2-trichloroethane	79-00-5		50.0	U
tetrachioroethene	127-18-4		50.0	U
1.3-dichloropropane	142-28-9		50.0	U
dibromochloromethane	124-48-1		50.0	U
1,2-dibromoethane	106-93-4		50.0	U
chlorobenzene	108-90-7		50.0	U
1,1,1.2-tetrachloroethane	630-20-6		50.0	U
ethylbenzene	100-41-4		50.0	U
m/p-xylene	106-42-3	103	5.0	
o-xylene	95-47-6	84.0	5.0	
styren e	100-42-5	2.8	5.0	K
bromoform	75-25-2		50.0	U

TDL-Target Detection Limit CAS#-Chemical Abstract Service Number

Guthrie Center Laboratory WVDEP-OWR

Client ID: Office of Waste Management

Date/Time Sampled:
Date Received:

3/1/95 @ 1230

Sample ID: Lab ID: IV-591030-P GCL9502102

Date/Time Analyzed:

3/3/95 3/7/95 @ 1416

Sampled by:

P. L. Brown/K. McCandless

Analyzed by:

Dan Arnold

Project ID:

RCRA

Method: SW846 Method 8260/EPA Method 624

		Result	<u>TDL</u>	<u>Data</u>
Compound	CAS#	<u>µg/L</u>	μg/L	Qualifier
isopropyłbenzene	98-82-8		50.0	U
bromobenzene	108-86-1	23.4	5.0	В
1,1,2,2-tetrachloroethane	79-34-5		50.0	U
1,2,3-trichloropropane	96-18-4		50.0	U
n-propylbenzene	103-65-1	9.4	5.0	
2-chiorotoluene	95-49-8		50.0	U
4-chlorotoluene	106-43-4		0.02	U
1,3,5-trimethylbenzene	108-67-8	44.0	5.0	
tert-butylbenzene	98-06-6		50.0	U
1.2,4-trimethylbenzene	95-63-6	17.5	5.0	
sec-butylbenzene	135-98-8		50.0	U
1,3-dichlorobenzene	541-73-1		50.0	U
p-isopropyttoluene	99-87-6	13.5	5.0	
1,4-dichlorobenzene	106-46-7		50.0	U
1,2-dichlorobenzene	95-50-1		50.0	U
n-butylbenzene	104-51-8	14.5	5.0	
1,2-dibromo-3-chloropropane	96-12-8		50.0	U
1,2,3-trichlorobenzene	87-61-6		50.0	U
hexachlorobutadiene	87-68-3		50.0	U
naphthalene	91-20-3	19.4	5.0	
1.2,4-trichlorobenzene	120-82-1		50.0	U

TDL-Target Detection Limit
CAS#-Chemical Abstract Service Number

Approved:

Guthrie Center Laboratory WVDEP-OWR

Client ID:

Office of Waste Management

Date/Time Sampled:

Date Received:

3/1/95 @ 1230

3/3/95

Sample ID:

IV-591030-P

Lab ID:

GCL9502102

Sampled by:

P. L. Brown/K. McCandless

Project ID:

RCRA

Tentatively Identified Compounds

	rematively identified bottom	Journas	
			Result
CAS#	Compound	<u>Method</u>	<u> 1/64</u>
124-18-5	Decane	8260	57
622-96-8	1-ethyl-4-methyl benzene	8260	89
1074-43-7	1-methyl-3-propyl benzene	8260	51
1120-21-4	Undecane	82 60	171
1758-88-9	2-ethyl-1,4-dimethyl benzene	8260	55
527-84-4	1-methyl-2-(1-methylethyl) benzene	8260	86
99-87-6	1-methyl-4-(1-methylethyl) benzene	8260	80
2039-89-6	2-ethenyl-1,4-dimethyl benzene	826 0	68
2039-90-9	2-ethenyl-1,3-dimethyl benzene	8260	146
112-40-3	Dodecane	8260	207
119-64-2	1,2,3,4-tetrahydro-naphthalene	8260	98
3877-19-8	1,2,3,4-tetrahydro-2-methyl-naphthalene	826 0	53
17312-60-6	6-ethyl undecane	8260	59
2809-64-5	1,2,3,4-tetrahydro-5-methyl-naphthalene	8260	63
629-50-5	Tridecane	8260	266
1680-51-9	1,2,3,4-tetrahydro-6-methyl-naphthalene	8260	312
26730-12-1	4-methyl tridecane	8260	53
91-57-6	2-methyl naphthalene	8260	348
3891-98-3	2,6,10-trimethyl dodecane	8260	104
629-59-4	tetradecane	8260	254

Approved:

James A. Cambbell, PhD

Data Qualifier Legend

- U Indicates that the parameter was analyzed for but not detected.
- J Indicates the presence of a parameter which met the identification criteria but was present at a concentration less than the method detection limit (MDL).
- K Indicates the presence of a parameter at a concentration above the MDL but less than the lowest concentration level of the calibration table.
- B Indicates that the parameter was present in the method blank as well as the sample. The reported result should be viewed with caution and should be considered to be of questionable value.
- X Indicates that the parameter was identified and/or quantitated after the designated holding time specified in the methodology. The reported value is for informational puposes only.
- Note 1: The laboratory has established minimum target values for each parameter. These values reflect the lower limits that the laboratory expects to achieve on routine samples and for which there is a high level of confidence in the results. These are not necessarily the method or instrument detection limits. The actual detection limits used with the "U" qualifier will be dependent on the particular sample and the concentration/dilution actions required to perform the analyses within the working range of the instrument(s). The detection limits(TDL/MDL) for a sample will be the minimum target values or some multiple of the minimum target values.
- Note 2: The reported results are not corrected for recoveries.

WEST VIRGINIA DIVISION OF ENVIRONMENTAL PROTECTION GUTHRIE CENTER LABORATORY

ORGANICS SAMPLE SUBMISSION FORM

ogram: NPI mpling Site I	DES CER	TY-5910	RA _												
- 10									_		Permit No.				
Preservati	Purgeables 601 Halocarbo 602 Aromatics 624 Volatiles 8240 Volatiles* ve:	□ 6 □ 82	Parameters Base-Neutral-Acid Extractables 625 Semivolatiles 8270 Semivolatiles Preservative:						Organochlorine Pesticides/PCBs 608 Wastewater Method 8080 Solid Waste Method Preservative:						
mples	r	, <u></u>		Composite	Grab	# of Containers	Water	Soil / Sediment	liO	Other		ness	:	<i>¥3</i> ₄	Comments
Field No.		Longitude	Laboratory No.			5	Samp	ole N	/atrix	κ					
01			GCL-	X		a				X	3/1/96	Ø)	1230		
	¥.		GCL-						_		•				
			GCL-												
			GCL-						<u></u>						
			GCL-											<u> </u>	7
			GCL-												
			GCL-											<u> </u>	
			GCL-												
			GCL-												
			GCL-	-											
			GCL-						<u> </u>					<u></u>	
Relinquished by: (Signature) Date / Time Recei Recei		Received by: (Signature)	sived by: (Signature)			Relinquished by: (Signature				re) Date / Time		Rec	eived by: (Signature)		
Relinquished	by: (Signature)	Date / Time	Received by: (Signature)			Relin	quish	ed by	y: (Sī	gnatu	ire)	Da	ite / Time	Rec	eived by: (Signature)
Relinquished	by: (Signature)	Date / Time	Received for Laboratory by,		ure)	.2		e / Ti	ime		Remarks آسين خان پر	. :	÷	دمامد	

STATE OF WEST VIRGINIA DEPARTMENT OF NATURAL RESOURCES

RECEIPT FOR SAMPLES

Project Number Project Name or Code					Code	P	Name of Fa				
IV-591030-P							Coyne Textile Services				
Samplers (Signature) ABrown								<u> </u>			
Split Sam	ples Offere	ed /	116	m n	<u> </u>		Facility Loc		// /.	/	
Accepted Declined								1111 Vernon of	tunting	iton, w	
Station Number	Date	Time	Сошр.	Grab	Split Samples	Tag Numbers		Station Description	No. of Con- tainers	Remarks	
01	3/1/95	12:30	X		Y			UST.	a	VOX's	
								·			
Transferre	d by (Sign	ature)	Car	reli	1/	- Ogden Er	iviron.	Received by (Signature)		Telephone 704-256-6850	
Date 3/	11/95					Time 1245		Title Cor. Dozeator	Date 3/1/	Time	

ATTACHMENT 2: OGDEN SAMPLE RESULTS FOR UST

P.01

OGDEN

FACSIMILE TRANSMITTAL

TO

ENVIRONMENTAL & ENERGY SERVICES CO.

3211 Jermantown Road

Fax Number: (703) 246-0939

Fairfax, Virginia 22030

(703) 246-0309

PLEASE DELIVER THE FOLLOWING PAGES TO:

NAME:

Penny Brann

COMPANY:

FAX NUMBER:

364-256-6755 0 6948

FROM:

KRIS K. McCANDLESS

DATE:

5/12/95

Total number of pagest including cover page. If all pages are not received, please call 703-246**-**0500:

0304

Attached are total Halgenand Valetiles (8010) results and TPH-Results for the UST tankliquids sample.

Report coming soon!

ANALYTICAL TECHNOLOGIES, INC.

11 East Olive Road Pensacola, Florida 32514 (904) 474-1001

TO

[0] Page 1 Date 17-Mar-95

"FINAL REPORT FORMAT - SINGLE"

Accession: Client:

503244 OGDEN ENVIRONMENTAL AND ENERGY SERVICES CO., INC. 0-7066-0000-0002

Project Number: Project Name: Project Location:

Project Name: 0-705-000-0002
Project Name: CTS-HUNTINGTON, WV
Project Location: HUNTINGTON, WV
Test: TCO / PETRO. HYDROCARBON RANGE C6-C32
Analysis Method: 8015 / SW 846, 3rd Edition, September 1986 and Revision 1, July 1992
Extraction Method: 3510/SW-846, 3rd Edition, September 1986 and Revision 1, July 1992
Matrix: LIQUID

OCCUPATION OF THE PROJECT OF THE PROJEC

I

OC Level:

001

Sample Date/Time:

01-MAR-95 N/S

Lab Id: Client Sample Id:

UST-1

Received Date:

03-MAR-95

Batch: FPW043 Blank: A

Dry Weight %:

Extraction Date: Analysis Date:

08-MAR-95 10-MAR-95

Parameter:

UG/L

N/A

Results:

Rpt Lmts:

Q:

TOTAL PETROLEUM HYDROCARBON HYDROCARBONS QUANTITATED USING ORTHO TER PHENYL ANALYST

Units:

290000

10000

(+) N/A REC/SURR D INITIALS

SJF

37-140

Comments:

D = DILUTED OUT. (+) DIESEL RANGE C10-C28.

BROMOBENZENE

CHLOROACETALDEHYDE

2-CHLOROTOLUENE

CHLOROMETHYLMETHYL ETHER

11 East Olive Road Pensacola, Florida 32514 (904) 474-1001

[0] Page 1 Date 15-Mar-95

"FINAL REPORT FORMAT - SINGLE"

503244 Accession: OGDEN ENVIRONMENTAL AND ENERGY SERVICES CO., INC. Client: 0-7066-0000-0002 Project Number: Project Name: Project Location: CTS-HUNTINGTON, WV HUNTINGTON, WV HALOGENATED VOLATILES (8010) Test: Analysis Method: 8010 / SW 846, 3rd Edition, September 1986 and Revision 1, July 1992 Extraction Method: N/A LIQUID Matrix: QC Level: Ĭ Lab Id: 001 Sample Date/Time: 01-MAR-95 N/S Client Sample Id: UST-1 Received Date: 03-MAR-95 Batch: LUW039 Blank: B Extraction Date: N/A 15-MAR-95 Dry Weight %: N/A Analysis Date: Parameter: Units: Results: Rpt Lmts: Q; BROMODICHLOROMETHANE UG/L ND BROMOFORM UG/L ND 2 BROMOMETHANE UG/L ND 2 CARBON TETRACHLORIDE CHLOROBENZENE UG/L ND 1 UG/L ND 1 CHLOROETHANE UG/L 5 ND 2-CHLOROETHYLVINYLETHER UG/L ND 52552225 CHLOROFORM UG/L ND CHLOROMETHANE UG/L ND DIBROMOCHLOROMETHANE UG/L ND 1,2-DICHLOROBENZENE UG/L ND 1,3-DICHLOROBENZENE 1,4-DICHLOROBENZENE UG/L ND UG/L ND DICHLORODIFLUOROMETHANE UG/L ND 1,1-DICHLOROETHANE 1,2-DICHLOROETHANE UG/L ND 1 UG/L ND 1,1-DICHLOROETHENE 1,2-DICHLOROETHENE (TOTAL) ī 1 UG/L ND UG/L ND 1,2-DICHLOROPROPANE UG/L ND CIS-1,3-DICHLOROPROPENE TRANS-1,3-DICHLOROPROPENE METHYLENE CHLORIDE ī UG/L ND UG/L ND UG/L ND 5 1,1,2,2-TETRACHLOROETHANE TETRACHLOROETHENE UG/L 1 ND UG/L ND 3 1,1,1-TRICHLOROETHANE 1,1,2-TRICHLOROETHANE UG/L ND 12 UG/L ND TRICHLOROETHENE UG/L ND TRICHLOROFLUOROMETHANE UG/L 2 ND VINYL CHLORIDE UG/L ND 1 UG/L++ BENZYL CHLORIDE BIS 2-CHLOROETHOXY METHANE BIS 2-CHOROISOPROPYL ETHER 5 ND 50 ND UG/L** ND 50

UG/L**

UG/L**

UG/L**

UG/L**

ND

ND

ND

ND

50

50

ANALYTICAL TECHNOLOGIES, INC. 11 East Olive Road Pensacola, Florida 32514 (904) 474-1001

[0] Page 2 Date 15-Mar-95

P.04

"FINAL REPORT FORMAT - SINGLE"

Accession:

503244 OGDEN ENVIRONMENTAL AND ENERGY SERVICES CO., INC. 0--7066--0000--0002Client:

Project Number: Project Name: Project Location:

CTS-HUNTINGTON, WV HUNTINGTON, WV HALOGENATED VOLATILES (8010) Test:

8010 / SW 846, 3rd Edition, September 1986 and Revision 1, July 1992 Analysis Method:

Extraction Method: N/A Matrix: LIQUID

Matrix: QC Level:

I

Lab Id: Client Sample Id: 001 Sample Date/Time: 01-MAR-95 N/S UST-1 Received Date: 03-MAR-95

Units: Results: Parameter: Rpt Lmts: Q١ UG/L** UG/L** UG/L** DIBROMOMETHANE ND 5 1,1,1,2-TETRACHLOROETHANE 1,2,3 TRICHLOROPROPANE 1-CHLOROHEXANE ND 1 5 ND UG/L++ %REC/SURR ND BROMOFLUOROBENZENE (ELCD) 83 75-137 ANALYST INITIALS SR

Comments:

ATTACHMENT 3: PHOTOS & PHOTO LOG




PHOTO LOG

Facility Name: Coyne Textile Services Location: Huntington, WV (Wayne Co.)

1	2	3	4	5	6
1	Kodacolor Gold DX 400 Exp 5/96	fixed	Cloudy/ cool	3/1/95	Sample being collected through one of the UST ports. Sample of UST contents in 1 liter jar and in VOAs in background.
2				я н	Photo taken by boiler room door. Burn marks on piece of wooden hopper used to contain shop rags.
3		• •	• •	и ж	Photo taken by boiler room door. Remains of burned wooden hopper at Left, burned shop rag on concrete.
4				aj m	Charred pieces of rags on gravel near UST, just above boiler room door.

Photographer's Signature:_

1. Photo Number

2. Film Description

3. Focal Length/F-Stop/Shutter Speed

4. Weather

5. Date/Time

6. Description of Photo

FILM TURNED OVER TO: Foto 1--Crossroads Mall

FOR DEVELOPING ON: 4/5/95 RECEIVED ON: 4/5/95